

E2335 Barnhart Dr. Waupaca , WI 54981

6/5/2024 4:09:14 PM

E2335 Barnhart Dr. Page 1 of 21

Table of Contents

Definitions	2
Inspection Agreement	2
General Information	2
Lots and Grounds	3
Exterior	4
Air Conditioning	5
Roof	5
Garage	7
Kitchen	7
Living Space	8
Fireplace	9
Bathroom	10
Bedroom	11
Attic	12
Laundry Room	12
Crawlspace	13
Structure	14
Plumbing	14
Heating System	15
Electrical	16
Summary	17

6/5/2024 4:09:14 PM

920-716-8395

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection
 Acceptable Functional with no obvious signs of defect.
 Not Present Item not present or not found.
 Not Inspected Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.
 Marginal Item shows wear, aging, not in it's original condition and/or may need typical home ownership maintenance
 Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Inspection Agreement

General Information

Property Information

Property Address E2335 Barnhart Dr. City Waupaca State WI Zip 54981 Client Name Phone

Client Information

E-Mail NA

Inspection Company

Inspector Name Frank Freiburger Company Name Top Notch Home and Foundation Inspections E-Mail ffrei@hotmail.com Amount Received 0

Conditions

Others Present None Property Occupied Vacant Estimated Age 1999 Entrance Faces East Inspection Date 2024-06-05 Start Time 1:30PM End Time 4:10PM Electric On Yes Gas/Oil On Yes Water On Yes Temperature 77 Degrees Weather Sunny Soil Conditions Wet Building Type Single family Garage Detached

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 3 of 21

General Information (Continued)

Referrer Name Lori Verhalen

Lots and Grounds

- 1. Acceptable Driveway: Asphalt
- Walks: Concrete 2. Acceptable
- Steps/Stoops: Wood 3. Acceptable
- 4. Marginal

Grading: Negative slope - All grading on the exterior of the house should have a minimum slope of one inch per foot for the first four feet away from the foundation. A 5-10 mil plastic should

then be installed on top covered with stones or mulch for aesthetics. This will help direct water away from the house to help lower the chance of water from entering the basement and reduce hydrostatic pressure on the foundation walls the future. Lack of maintenance on the exterior grading and gutters is the number one cause of foundation problems.



Vegetation: Shrubs/Trees - Recommend trimming to prevent damage to the exterior of the 5. Acceptable house.

6. Acceptable



6/5/2024 4:09:14 PM

E2335 Barnhart Dr. Page 4 of 21

Exterior	
All sides Exterior	r Surface
1. Acceptable	Type: Vinyl
2. Marginal	Trim: Aluminum/Vinyl/Wood - Wood rot damage present
2 Marginal	Soffite/Facele Aluminum Dente noted
3. Marginal	Soffits/Fascia Aluminum - Dents noted
4. Marginal	Entry Doors: Metal/Wood - Surface laminate cracking and peeling. Water damaged
5. Marginal	Windows: Vinyl - Loose molding, past putty repair
5. Marginar	Windows some/all still original from when the building was built. It may be desirable to replace all old windows

6. Acceptable

7. Acceptable 8. Acceptable

Exterior Lighting: Surface mount Exterior Electric Outlets: 110 VAC GFCI

Window Screens: Vinyl mesh

9. Acceptable Hose Bibs: Frost Free

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 5 of 21

Exterior (Continued)

10. Acceptable Gas Meter: Exterior surface mount at side of home11. Acceptable Main Gas Valve: Located at gas meter

Air Conditioning

Main AC System -

- 1. Acceptable A/C System Operation: Limited cooling The unit is currently in service beyond the manufactures stated design life, but was cooling at the time of the inspection
- 2. Acceptable Condensate Removal: Plastic tubing
- 3. Acceptable Exterior Unit: Pad mounted
- 4. Manufacturer: Goodman



- 5. Area Served: Whole building Approximate Age: 1999
- 6. Acceptable Visible Coil: Copper core with aluminum fins
- 7. Acceptable Electrical Disconnect: Breaker disconnect

Roof

Main Roof Surface -

1. Method of Inspection: On roof



2. Acceptable

Unable to Inspect: 0% Material: Asphalt shingle

Acceptable
 Type: Gable

Palm-Tech Inspector, Copyright © 1998-2024, Palm-Tech

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 6 of 21

Roof (Continued)

- 5. Approximate Age: 3 to 5 years
- 6. Acceptable Flashing: Metal/Rubber
- 7. Acceptable Valleys: Asphalt shingle
- 8. Acceptable Plumbing Vents: Plastic
- 9. Defective

Skylights: Insulated glass - Fogging present in the glass due to broken seal



10. Acceptable

Electrical Mast: Underground utilities



11. Marginal

Gutters/Downspouts Aluminum/Metal - Recommend adding gutters to help keep water away from the structure and lowering the chance of foundation and/or water damage



Acceptable
 Center Chimney
 Acceptable

Extensions: Satisfactory

Chimney: Metal



14. Not Inspected Flue/Flue Cap: Metal - Chimney lining could not be inspected due to rain cap 15. Acceptable Chimney Flashing: Metal

Top Notch Home and Foundation Inspections

920-716-8395

E2335 Barnhart Dr. Page 7 of 21

Garage

Detached Garage -

- 1. Type of Structure: Detached Car Spaces: 3
- 2. Acceptable Garage Doors: Metal
- 3. Acceptable Door Operation: Mechanized
- 4. Acceptable Exterior Surface: Vinyl
- 5. Marginal Roof: Asphalt shingle Roof near end of useful life with higher percentage of grandulars missing. Roof may need to be replaced in the next five years.



- 6. Not Present Gutters/Downspouts None Recommend adding gutters to help keep water away from the structure and lowering the chance of foundation and/or water damage
- 7. Acceptable Service Doors: Metal
- 8. Acceptable Ceiling/Walls Exposed framing
- 9. Acceptable Windows: Vinyl
- 10. Acceptable Floor/Foundation: Poured concrete
- 11. Defective Electrical: 110 VAC & 110 VAC GFCI At the time this garage was built proper code would have been all outlet should be GFCI protected

Kitchen

- 1st Floor Kitchen -
- 1. Acceptable Cooking Appliances: Kenmore
- 2. Acceptable Exhaust Fan Broan
- 3. Defective

Dishwasher: General Electric - Properly secure to counter/base cabinets
 The dishwasher made strange noises when turning on, so it was not tested. Recommend repair




- 4. Air Gap Present? No
- 5. Acceptable Refrigerator: Frigidaire
- 6. Acceptable Sink: Stainless Steel
- 7. Acceptable Electrical: 110 VAC & 110 VAC GFCI
- 8. Acceptable Plumbing/Fixtures: Chrome/Plastic

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 8 of 21



14. Acceptable Windows: Vinyl

Living Space

Dining Room Living Space -

1. Acceptable Ceiling/Walls Paint/Paneling

- 2. Acceptable Floor: Carpet
- 3. Acceptable Doors: None
- 4. Marginal

Windows: Vinyl - The counter balance mechanism is broken/not hooked up. Chips, flacking inside layers of glass.

Windows some/all still original from when the home was built. It may be desirable to replace all old windows



5. Acceptable Electrical: 110 VAC

6. Acceptable HVAC Source: Heating system register

Living Room Living Space -

- 7. Acceptable Ceiling/Walls Paint/Paneling
- 8. Acceptable Floor: Carpet
- 9. Acceptable Doors: Wood/Metal
- 10. Marginal Windows: Vinyl The counter balance mechanism is broken/not hooked up
- 11. Acceptable Electrical: 110 VAC
- 12. Acceptable HVAC Source: Heating system register

Guests Living Room Living Space -

Top Notch Home and Foundation Inspections

920-716-8395

Living Space (Continued)

- 13. Marginal
- Ceiling/Walls Paint This area of the home is built on a poured slab. Staining present from possible exterior moisture coming in. Recommend improving exterior grade to keep all water away from home



- 14. Acceptable Floor: Carpet Carpet Stained/soiled
- 15. Acceptable Doors: Metal
- 16. Acceptable Windows: Vinyl
- 17. Acceptable Electrical: 110 VAC & 110 VAC GFCI
- 18. Acceptable HVAC Source: Heating system register

Fireplace

Living Room Fireplace

1. Defective Fire

Fireplace Construction: Prefab - The fireplace would not fire at the time of the inspection. Recommend verifying with the sellers that is works, or recommend repair



- 2. Type: Gas log
- 3. Acceptable Fireplace Insert: Standard
- 4. Acceptable Smoke Chamber: Brick
- 5. Acceptable Flue: Metal
- 6. Acceptable Damper: Metal
- 7. Acceptable Hearth: Raised

6/5/2024 4:09:14 PM

E2335 Barnhart Dr. Page 10 of 21

Bathroom

Master Bathroom)
1. Acceptable	Ceiling/Walls Paint/Paneling
2. Acceptable	Floor: Luxury Vinyl - The floor squeaks when walked on
3. Acceptable	Doors: Wood
4. Acceptable	Electrical: 110 VAC GFCI
5. Acceptable	Faucets/Traps: Twin handles
6. Acceptable	Tub Fiberglass tub
7. Acceptable	Surround Fiberglass
8. Acceptable	Toilets: Satisfactory
9. Acceptable	HVAC Source: Heating system register
10. Acceptable	Ventilation: Electric vent fan
Lower Bathroom	
11. Acceptable	Ceiling: Paint
12. Acceptable	Walls: Paint
13. Acceptable	Floor: Linoleum
14. Acceptable	Doors: Wood
15. Acceptable	Electrical: 110 VAC GFCI
16. Acceptable	Faucets/Traps: Single handle
17. Acceptable	Shower/Surround: Fiberglass
18. Acceptable	Toilets: Satisfactory
19. Acceptable	HVAC Source: Heating system register
20. Acceptable	Ventilation: Electric ventilation fan
1st floor Main Ba 21. Acceptable	Ceiling/Walls Paint/Paneling
22. Acceptable	Floor: Linoleum
23. Acceptable	Doors: Wood
24. Acceptable	Electrical: 110 VAC GFCI
25. Acceptable	Faucets/Traps: Twin handles
26. Acceptable	Tub/Surround: Fiberglass tub
27. Acceptable	Shower/Surround: Fiberglass
28. Acceptable	Toilets: Satisfactory
29. Acceptable	HVAC Source: Heating system register
30. Acceptable	Ventilation: Electric ventilation fan

6/5/2024 4:09:14 PM

E2335 Barnhart Dr. Page 11 of 21

Bedroom	
Master Bedroom 1. Acceptable 2. Acceptable 3. Acceptable 4. Acceptable 5. Acceptable 6. Acceptable 7. Not Present SE Bedroom 8. Acceptable 9. Acceptable	Ceiling/Walls Paint/Paneling Floor: Carpet Doors: Wood Windows: Vinyl Electrical: 110 VAC HVAC Source: Heating system register Smoke Detector:
	Ceiling/Walls Paint/Paneling Floor: Carpet - Carpet Stained/soiled
 Acceptable Acceptable Acceptable Acceptable Acceptable Acceptable Not Present SE Bedroom Acceptable Acceptable	Doors: Wood Windows: Vinyl Electrical: 110 VAC HVAC Source: Heating system register Smoke Detector:
	Ceiling/Walls Paint/Paneling Floor: Carpet Doors: Wood Windows: Vinyl - The counter balance mechanism is broken/not hooked up Electrical: 110 VAC HVAC Source: Heating system register Smoke Detector:
	Ceiling/Walls Paint Floor: Carpet Doors: Wood Windows: Vinyl Electrical: 110 VAC HVAC Source: Heating system register Smoke Detector:

Top Notch Home and Foundation Inspections

920-716-8395

E2335 Barnhart Dr. Page 12 of 21

Attic

Entire attic Attic -

1. Method of Inspection: From the attic access



- 2. Acceptable Unable to Inspect: 70% - Cathedral or vaulted ceiling, Limited visibility, and access
- 3. Acceptable Roof Framing: 2x4 Truss
- Sheathing: OSB 4. Acceptable
- Ventilation: Ridge and soffit vents 5. Acceptable
- 6. Acceptable **Insulation:** Fiberglass
- 7. Acceptable Insulation Depth: 8 to 12 inches



Laundry Room

1st Floor Laundry Room/Area -

- 1. Acceptable Ceiling/Walls Paint/Paneling
- 2. Acceptable Floor: Linoleum
- 3. Acceptable Electrical: 110 VAC
- 4. Defective
 - Washer/Dryer General Electric The washing machine would not work at the time of the inspection. Recommend verifying that it works, or recommend repair



5. Acceptable

Washer and Dryer Electrical: 110-240 VAC Dryer Vent: Metal

- 6. Acceptable
- 7. Acceptable Washer Drain: Wall mounted drain

Top Notch Home and Foundation Inspections

920-716-8395

E2335 Barnhart Dr. Page 13 of 21

Crawlspace

Crawlspace Crawlspace

- 1. Acceptable, Not Inspected Unable to Inspect: 30% Limited visibility, access
- 2. Acceptable Ceiling/V



Acceptable Acceptable

Floor: Poured

Moisture Location: No water was present at the time of the inspection. All grading on the exterior of the house should have a minimum slope of one inch per foot for the first four feet away from the foundation. A 5-10 mil plastic should then be installed on top covered with stones or mulch for aesthetics. This will help direct water away from the house to help lower the chance of water from entering the basement and reduce hydrostatic pressure on the foundation walls the future. Lack of maintenance on the exterior grading and gutters is the number one cause of foundation problems.

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 14 of 21

Structure

- 1. Acceptable Structure Type: Wood
- 2. Acceptable Foundation: Poured slab on concrete Block
- 3. Acceptable Differential Movement: No movement or displacement noted
- 4. Acceptable Beams: Steel
- 5. Acceptable Bearing Walls: Wood
- 6. Acceptable Joists/Trusses: Steel
- 7. Acceptable Piers/Posts: Concrete block
- 8. Not Inspected Subfloor: Not visible Covered with plastic, not visible

Plumbing

- 1. Acceptable Service Line: Copper
- 2. Acceptable

Main Water Shutoff: Utility closet



- 3. Acceptable Water Lines: Copper
- 4. Acceptable Drain Pipes: ABS and PVC
- 5. Not Inspected Service Caps: Not visible Not visible
- 6. Acceptable Vent Pipes: PVC
- 7. Acceptable Gas Service Lines: Black Iron
- Utility Closet Water Heater -
- 8. Acceptable Water Heater Operation: Functional at time of inspection
- 9. Manufacturer: Rheem



- 10. Type: Electric Capacity: 40 Gal.
- 11. Approximate Age: 1998 Area Served: Whole building
- 12. Acceptable TPRV and Drain Tube: Copper

Top Notch Home and Foundation Inspections 920-716-8395

E2335 Barnhart Dr. Page 15 of 21

Heating System

Utility Closet Heating System

1. Acceptable Heating System Operation: Adequate - Furnace existing beyond design life but was operating at acceptable levels at the time of the inspection



2. Manufacturer: Unknown manufacturer



- 3. Area Served: Whole building Approximate Age: 1998
- 4. Fuel Type: Natural gas
- 5. Not Inspected Heat Exchanger: 1 Burner Heat exchanger not visible on this type of furnace
- 6. Unable to Inspect: 100%
- 7. Acceptable Blower Fan/Filter: Direct drive with disposable filter
- 8. Acceptable Distribution: Metal and Insulflex
- 9. Acceptable Flue Pipe: Metal
- 10. Not Present Controls: Shut off switch Not visible
- 11. Acceptable Thermostats: Individual
- 12. Suspected Asbestos: No

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 16 of 21

Electrical

- 1. Service Size Amps: 200 Volts: 110-240 VAC
- 2. Acceptable Service: Aluminum
- 3. Acceptable 120 VAC Branch Circuits: Copper
- 4. Acceptable Conductor Type: Romex
- 5. Acceptable Ground: Present
- 6. Marginal Smoke/C.O. detectors Present in some areas Recommend C.O and smoke detectors be present on every level of the home

Recessed in wall Electric Panel -

- 7. Maximum Capacity: 100 Amps
- 8. Acceptable Main Breaker Size: 200 Amps



9. Acceptable



10. Is the panel bonded? Yes

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 17 of 21

Marginal Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

1. Grading: Negative slope - All grading on the exterior of the house should have a minimum slope of one inch per foot for the first four feet away from the foundation. A 5-10 mil plastic should then be installed on top covered with stones or mulch for aesthetics. This will help direct water away from the house to help lower the chance of water from entering the basement and reduce hydrostatic pressure on the foundation walls the future. Lack of maintenance on the exterior grading and gutters is the number one cause of foundation problems.



Exterior

2. Trim: Aluminum/Vinyl/Wood - Wood rot damage present



3. Soffits/Fascia Aluminum - Dents noted



4. Entry Doors: Metal/Wood - Surface laminate cracking and peeling. Water damaged

6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 18 of 21

Exterior (Continued)

Entry Doors: (continued)



5. Windows: Vinyl - Loose molding, past putty repair Windows some/all still original from when the building was built. It may be desirable to replace all old windows



Roof

6. Gutters/Downspouts Aluminum/Metal - Recommend adding gutters to help keep water away from the structure and lowering the chance of foundation and/or water damage



Garage

7. Detached Garage Roof: Asphalt shingle - Roof near end of useful life with higher percentage of grandulars missing. Roof may need to be replaced in the next five years.



6/5/2024 4:09:14 PM

920-716-8395

Marginal Summary (Continued)

Living Space

8. Dining Room Living Space Windows: Vinyl - The counter balance mechanism is broken/not hooked up. Chips, flacking inside layers of glass.

Windows some/all still original from when the home was built. It may be desirable to replace all old windows



- 9. Living Room Living Space Windows: Vinyl The counter balance mechanism is broken/not hooked up
- 10. Guests Living Room Living Space Ceiling/Walls Paint This area of the home is built on a poured slab. Staining present from possible exterior moisture coming in. Recommend improving exterior grade to keep all water away from home



Bedroom

- 11. SE Bedroom Windows: Vinyl The counter balance mechanism is broken/not hooked up Electrical
- 12. Smoke/C.O. detectors Present in some areas Recommend C.O and smoke detectors be present on every level of the home

6/5/2024 4:09:14 PM

920-716-8395

Defective Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Roof

1. Skylights: Insulated glass - Fogging present in the glass due to broken seal



Garage

2. Detached Garage Electrical: 110 VAC & 110 VAC GFCI - At the time this garage was built proper code would have been all outlet should be GFCI protected

Kitchen

3. 1st Floor Kitchen Dishwasher: General Electric - Properly secure to counter/base cabinets The dishwasher made strange noises when turning on, so it was not tested. Recommend repair



Fireplace

4. Living Room Fireplace Fireplace Construction: Prefab - The fireplace would not fire at the time of the inspection. Recommend verifying with the sellers that is works, or recommend repair



6/5/2024 4:09:14 PM

920-716-8395

E2335 Barnhart Dr. Page 21 of 21

Defective Summary (Continued)

Laundry Room

5. 1st Floor Laundry Room/Area Washer/Dryer General Electric - The washing machine would not work at the time of the inspection. Recommend verifying that it works, or recommend repair

