

Home inspection repairs from attached report that was conducted on June 2, 2016

11. The water heater in the laundry room as been reprogrammed and is working properly.
12. The water heater that is presently in the closet in the living room is an older water heater and was intended to be disconnected, piped to the laundry room water heater and the space made into an entrance closet.
14. The pellet stove and been taken apart and re-vented.
19. Both toilets have been secured.