



NORTH CAROLINA
Environmental Quality

ROY COOPER
Governor

MICHAEL S. REGAN
Secretary

MICHAEL SCOTT
Director

Certified Mail 7019 2280 0000 6515 1315

February 2, 2021

Raleigh J. Pearson
Pearson's Service Center
667 NC Hwy 16 North
Taylorsville, NC 28110

**RE: Notice of No Further Action 15A NCAC 2L .0407(d)
Risk based Assessment and Corrective Action for Petroleum Underground Storage Tanks
Pearson's Service Center
667 NC Hwy 16 N
Taylorsville, Alexander County, NC (MRO)
STF Incident Number 40452
Risk/Rank: Low, L00R**

Dear Mr. Pearson:

Petroleum releases were identified at the referenced site when the underground storage tank system was removed on September 24, 2014. Up to 12,000 mg/kg gasoline-range Total Petroleum Hydrocarbons (TPH) were detected beneath the 2,000-gallon kerosene tank; 19,000 mg/kg diesel-range TPH was detected beneath the kerosene dispenser; and 3,100 diesel-range TPH was detected below the diesel dispenser. The site was recommended to the State Lead Cleanup Program in February 2020, and we have completed our assessment.

On January 29, 2021, the UST Section of the Division of Waste Management, Trust Fund Branch received an Initial Monitoring Report for the site. In December 2020, monitor wells were installed in each source area to collect groundwater and soil samples. No petroleum contaminated groundwater was detected above the level of the standards or interim standards established in 15A NCAC 2L .0202. In addition, no targeted compounds were detected in the soil above their respective Maximum Soil Contaminant Concentrations.

Based on information provided to date, the UST Section finds it appropriate to classify the risk of the discharge or release as low. Furthermore, the UST Section determines that no further action is warranted for this incident. This determination shall apply unless the UST Section later finds that this discharge or release poses an unacceptable risk or a potential risk to human health or environment, or additional information is provided to warrant reassessment of the site.




North Carolina Department of Environmental Quality | Division of Waste Management
217 West Jones Street | 1646 Mail Service Center | Raleigh, North Carolina 27699-1646
919.707.8200

Mr. Pearson
Pearson's Service Center, STF 40452
February 2, 2021

Pursuant to 15A NCAC 2L.0407(a), you have a continuing obligation to notify the UST Section of any changes that you know of, or should know of, that might affect the level of risk assigned to the discharge or release. Please be advised that the monitoring wells used to investigate this incident will be closed in accordance with 15A NCAC 2C .0113 and .0214, respectively by a State-Lead Contractor. If you have any questions concerning this notice, please contact Sharon Ghiold at sharon.ghiold@ncdenr.gov or 919-707-8166.

Thank you,



Wayne Randolph, CPM
Trust Fund Branch Head



North Carolina Department of Environmental Quality | Division of Waste Management
217 West Jones Street | 1646 Mail Service Center | Raleigh, North Carolina 27699-1646
919.707.8200