

ESTIMATE

ADVANCED CONCRETE LIFTING

1237 W Washington Ave
Gilbert, AZ 85233

info@aclaz.com
+1 (480) 560-8392
<http://advancedconcreteliftingaz.com>



Bill to

Stewart Larsen
The Larsen Company
2002 N 25th St.
Phoenix 85008

Ship to

Stewart Larsen
The Larsen Company
2002 N 25th St.
Phoenix 85008

Estimate details

Estimate no.: 1302
Estimate date: 06/17/2025

#	Date	Product or service	Description	Qty	Rate	Amount
1.		Sales	Lift and stabilize location across the front south and west side.		\$8,840.00	\$8,840.00
2.		Sales	Repair the cracks in the walls. East side, south side, and west side of home. Remove old crack mortar replace with new mortar for a solid repair.			\$2,400.00
3.		Sales	Stem wall repair approx. 20 feet at the east, south and west side of home. Excavate stem wall. Remove all loose and damaged material. Replace rebar as needed, treat any and all rebar with an epoxy rust inhibitor. Repair with structural patch material. Backfill dirt and rock.	25	\$130.00	\$3,250.00
					Total	\$14,490.00

Accepted date

Accepted by