

# SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

140 Sherman Street

CONCERNING THE PR	ROPI	ERTY	Y AT					R	usk	, Texa	s 75785			
AS OF THE DATE	SIG BUYE	ER N	) BY 1AY	WI:	SEL SH	LEF TO	R AND IS NOT	A S	SUB	STITU	CONDITION OF THE PRO TE FOR ANY INSPECTION RANTY OF ANY KIND BY S	NS	OF	₹
Property?						***************************************	(	appr	oxin	nate	now long since Seller has odate) or never occupi	occu ed	ipied the	d e
Section 1. The Proper This notice does	r <b>ty h</b> not e	<b>as th</b> stabli	e ite	ms e ite	ms t	rke to be	d below: (Mark Yes conveyed. The contra	ct w	, <b>No</b> ill de	(N), o	or Unknown (U).) e which items will & will not convey	<i>'</i> .		
Item	Y	N	U	ſ	Ite	m		Υ	N	U	Item	Y	N	U
Cable TV Wiring	V			Ì	Na	tura	I Gas Lines	1	1	+	Pump: sump grinder	┝┤	7	-0
Carbon Monoxide Det.		V		Ī	Fu	el G	as Piping:	*	V	$\forall$	Rain Gutters	.1	V	
Ceiling Fans	V			Ī		-	Iron Pipe	t	V		Range/Stove	V	-	
Cooktop	V			Ī	-Co	oppe	er .	1	Ť	V	Roof/Attic Vents	N. Alexander	$\dashv$	
Dishwasher	/						gated Stainless ubing			V	Sauna		V	
Disposal		V			Но	t Tu	b	1	200	,	Smoke Detector			
Emergency Escape Ladder(s)		1		Ī	Inte	ercc	m System		V		Smoke Detector - Hearing Impaired	$\prod$	V	
Exhaust Fans	V			f	Mic	crow	/ave	<del>                                     </del>	1/	+	Spa	$\vdash$	2	
Fences	V			1	Outdoor Grill			<del>                                     </del>	V		Trash Compactor	$\vdash$	V	
Fire Detection Equip.		V		Ī	Patio/Decking			1	8	1	TV Antenna	H	Y	
French Drain		<b>V</b>			Plumbing System			1		$\vdash$	Washer/Dryer Hookup	1	V	
Gas Fixtures	V			Ī	Pool			- V	V	$\vdash$	Window Screens	V	$\dashv$	
Liquid Propane Gas:		V		T	Po	ol E	quipment	<del>                                     </del>	J	H	Public Sewer System	V	$\dashv$	
-LP Community (Captive)		1					aint. Accessories		V		r abile dewel dystem	Y		
-LP on Property		<b>V</b>		E	Po	ol H	eater		V			H		
Item														
Central A/C				Y	N	U	9				nal Information			
Evaporative Coolers	··			6				nun	nbei	of uni	ts:			
Wall/Window AC Units			$\dashv$	$\dashv$	V		number of units:							
Attic Fan(s)				$\dashv$	Y		number of units:							
Central Heat				1	V		if yes, describe:			-				
Other Heat				V	1		electric v gas	nun	nbei	of uni	ts: /	·	-	
Oven				#	-		if yes, describe:			<i>M</i> .		_		
Fireplace & Chimney				8			number of ovens:	1_	1	elec				
Carport			12	1	6	-	Mood gas, log	-	·m		otpei.			- 1
Garage	************			1		$\dashv$	attachednot	-						
Garage Door Openers			V	-	-	-	✓ attachednot :	attac	hed					
Satellite Dish & Controls			-	+		$\dashv$	number of units:				number of remotes:			
Security System			-	+	1	$\dashv$	ownedleased							
				1			ownedleased	fror	n:	y /A	10			
(TXR-1406) 07-10-23	2		itiale	-	3			nd Se	ller:	LT.	Pag	je 1	of 7	_
United Country Real Estate East Texas Lar Timothy Sansom	nd and I Proc	tomes, 1 duced wi	190 S. M ith Lone	wolf	reet Ru Transa	sk TX	75785 s (zipForm Edition) 717 N Harwoo	d St, St	Pho uite 22	ne: 903683 00, Dallas,	3222 Fax: Kevin . TX 75201 <u>www.lwolf.com</u>	& Valli	amah	

Solar Panels			-/			1 16						
Water Heater	***************************************	2/	V		owned_	leased fr						
Water Softener		V	. //		electric_		other	:	number of units:			
Other Leased Items(s)			V		owned	leased fr	om:	*******		-		
Underground Lawn Sprinkler				s, descr					disposition was			
					automatic manual areas covered							
			V		if yes, attach Information About On-Site Sewer Facility (TXR-1407)							
covering)? yes <u>v</u> no	e 1978 and atta overing unknow	ach T) g on wn	ves <u>v</u> KR-190 the Pr	no )6 cond operty	unknowr cerning le Age: _ (shingle	ead-based 8 <u>V.R.</u> s or roof	pair S 🔌 cov	nt haza	ards).  Discoil (appropriate of the state of			
defects, or are need of repair	er) aw	rare c	no If y	defec	scribe (a	ttach addi	tiona	I shee	e not in working condition, the strain of the cessary):			
Item	YI	I	Item				ΤΥ	N	Item	Y	TN	
Basement	V	/	Floor	S			+-	V	Sidewalks	+	N	
Ceilings	4	-			/ Slab(s)	· · · · · · · · · · · · · · · · · · ·	+-	No.	Walls / Fences	+-	IV.	
Doors	V	$\dashv$		or Wall			1.7	V			V	
Driveways	V	-		ng Fixt			V	-	Windows		V	
Electrical Systems	V	No.					V	-	Other Structural Components		V	
Exterior Walls	V		Roof	bing Sy	/stems	***************************************	-	V				
Section 3. Are you (Sella and No (N) if you are not a	er) aw	vare (							(Mark Yes (Y) if you are	e aw	  /are	
Condition		<del></del>		- 15	( N. )							
Aluminum Wiring				- 1	N	Condition			Annual Control of the	Y	N	
Asbestos Components					- Y	Radon C	as				100	
Diseased Trees: oak wilt					- V	Settling			THE RESERVE OF THE PROPERTY OF		V	
Endangered Species/Habita	t on Dr	o o o uti			- V	Soil Mov					V	
Fault Lines	t on Pr	operty		_	V				ure or Pits		W	
					V							
Hazardous or Toxic Waste					E. Paris	Unplatted Easements					V	
Improper Drainage					IV,	Unrecorded Easements					16	
Intermittent or Weather Springs					300	Urea-formaldehyde Insulation					V	
Landfill					V	Water D	ama	ge No	t Due to a Flood Event		V	
Lead-Based Paint or Lead-Based Pt. Hazards					₩ <sup>200</sup>	Wetland		Prope	erty		V	
Encroachments onto the Pro					Web	Wood R					V	
Improvements encroaching of	on othe	ers' pro	perty		1	Active in	festa	ation c	of termites or other wood		$\Box$	
		<del></del>	****		4	destroyir					V	
Located in Historic District					V				t for termites or WDI	1	V.	
Historic Property Designation					V	Previous termite or WDI damage repaired					V	
Previous Foundation Repairs					V	Previous	Fire	s	10	Land.		
(TXR-1406) 07-10-23	Init	ialed h	v: Buve	er.		and S	aller	·	1 1/5			

United Country Real Estate East Texas Land and Homes, 190 S. Main Street Rusk TX 75785
Phone: 9036833222
Fax:
Timothy Sansom
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201
www.lwolf.com

Page 2 of 7

### 140 Sherman Street Rusk, Texas 75785

Previous Roof Repairs		Termite or WDI damage needing repair	
Previous Other Structural Repairs		Single Blockable Main Drain in Pool/Hot	
	V	Tub/Spa*	V
Previous Use of Premises for Manufacture of Methamphetamine			
or methamphetamine			
If the answer to any of the items in Section 3 is ye	es, explain (a	ttach additional sheets if necessary):	
*A single blockable main drain may cause a suction			
Section 4. Are you (Seller) aware of any it	em, equipm	ent, or system in or on the Property that is	in need
additional sheets if necessary):	disclosed li	n this notice? yes no If yes, explain	ı (attach
Section 5. Are you (Seller) aware of any or	f the follow	ing conditions?* (Mark Yes (Y) if you are aw	
check wholly or partly as applicable. Mark No	(N) if you ar	e not aware.)	vare and
Y N			
Present flood insurance coverage.			
Previous flooding due to a failure	ما مسمم سم		
water from a reservoir.	or breach	of a reservoir or a controlled or emergency re	elease of
Present flood insurance coverage.  Previous flooding due to a failure water from a reservoir.  Previous flooding due to a natural flooding due to a failure water from a reservoir.  Previous flooding due to a failure water flooding due to a natural floo	od event.		
Previous water penetration into a stru		Property due to a natural flood	
Located wholly partly in a 1		dplain (Special Flood Hazard Area-Zone A, V, /	
AO, AH, VE, or AR).	oo year noo	apiani (Special Flood Hazard Area-Zone A, V, /	A99, AE,
V Located wholly partly in a 500	)-year floodpl	ain (Moderate Flood Hazard Area-Zone X (shaded)	))
V Located wholly partly in a floo	odway	(Shaded)	))-
Located wholly partly in a floo			
Located wholly partly in a res			
if the answer to any of the above is yes, explain (a	attach additio	nal sheets as necessary):	*******
*If Buyer is concerned about these matters	s. Buver mai	consult Information About Flood Hazards (TXF	2444
For purposes of this notice:	., _wy or may	OSIOGIC IIIOI III GUOLI ABOUL FIOOU HAZAFAS (TXF	(1414).
	(A) is identifi	ed on the flood insurance rate map as a special flood ha	

which is designated as Zone A, V, A99, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding, which is considered to be a high risk of flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.

"500-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area, which is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding, which is considered to be a moderate risk of flooding.

"Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of Engineers.

(TXR-1406) 07-10-23

Initialed by: Buyer: \_

and Seller:

Page 3 of 7

## 140 Sherman Street k, Texas 75785

	140
Concerning the Property at	Rus

United Country Real Estate East Texas Land and Homes, 190 S. Main Street Rusk TX 75785

Timothy Sansom

"Flood insurance rate map" means the most recent flood hazard map published by the Federal Emergency Management Agency under the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seq.).

"Floodway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of a river or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as a 100-year flood, without cumulatively increasing the water surface elevation more than a designated height.

"Reservoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retain water or delay the runoff of water in a designated surface area of land.

provider,	. Have you (Seller) ever filed a claim for flood damage to the Property with any insurance including the National Flood Insurance Program (NFIP)?* yes no If yes, explain (attach sheets as necessary):
risk, a structu	
Administi	Have you (Seller) ever received assistance from FEMA or the U.S. Small Business ration (SBA) for flood damage to the Property?yesno If yes, explain (attach additional necessary):
Section 8 if you are	Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) not aware.)
Y N	Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time.
	Homeowners' associations or maintenance fees or associamenta. If you complete the fellowing
	Name of association:  Manager's name:  Fees or assessments are: \$
✓	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following:  Any optional user fees for common facilities charged? yes no If yes, describe:
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)
	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.
	Any condition on the Property which materially affects the health or safety of an individual.
_ ✓	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
	Any rainwater harvesting system located on the Property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.
TXR-1406)	07-10-23 Initialed by: Buyer:, and Seller: // Page 4 of 7

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Phone: 9036833222

Fax:

Concernin	g the Prop	erty at		Rusk, Texas 75785						
	The Pro retailer.	perty is located	in a propane gas syste	em service area owne	ed by a propane d	istribution system				
	Any por district.	tion of the Pro	operty that is located in	n a groundwater co	nservation district	or a subsidence				
If the answ	ver to any o	of the items in Se	ection 8 is yes, explain (a	ttach additional sheets	if necessary):					
	***************************************									
persons	who regi	ularly provide	ears, have you (Sel inspections and wh tions?yesno	o are either licens	sed as inspector	s or otherwise				
Inspection	Date	Туре	Name of Inspecto	r		No. of Pages				
			1							
Section 10 — Hor — Wild — Oth	<b>0. Check a</b> mestead dlife Manaq ner:	A buyer sho	n the above-cited reports uld obtain inspections fro on(s) which you (Seller Senior Citizen Agricultural	om inspectors chosen b currently claim for t — —	by the buyer.  the Property:  Disabled  Disabled Veteran  Unknown					
Section 11 with any i	1. Have y nsurance	ou (Seller) ev provider? 🗸 ye	er filed a claim for s	damage, other than	flood damage, t	to the Property				
champie,	an mound	ince claim of	ver received proceed a settlement or award aim was made? yes	in a legal process	dinal and not use	المحمد ممالة الم				
detector i	equireme	nis of Chapte	ave working smoke 766 of the Health a al sheets if necessary): _	detectors installed and Safety Code?*	unknown 🗸 no	vith the smoke yes. If no				
inclui in yo	ned in acco ding perform ur area, you	rdance with the re nance, location, and may check unkno	fety Code requires one-fam quirements of the building d power source requirements wn above or contact your loo	code in effect in the area s. If you do not know the k cal building official for mor	a in which the dwelling building code requireme re information.	g is located, ents in effect				
impa sellei	y wno wiii r irment from i r to install sr	eside in the dwell a licensed physicia noke detectors for	all smoke detectors for the I ing is hearing-impaired; (2) n; and (3) within 10 days afte the hearing-impaired and s ne smoke detectors and whice	the buyer gives the seller for the effective date, the bu pecifies the locations for	er written evidence of uyer makes a written red installation. The parties	the hearing				

(TXR-1406) 07-10-23

Initialed by: Buyer: and Seller:

Page 5 of 7

United Country Real Estate East Texas Land Homes, 190 S. Main Street Rusk TX 75785 Phone: 9036833222 Fax:
Timothy Sansom Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Page 6 of 7

phone #: \_\_\_\_\_ phone #: \_\_\_\_ phone #: \_\_\_\_\_

phone #:

phone #: 800 - 376 - 9663

phone #:

Kevin & Valliamah

(6) The following providers currently provide service to the Property:

Electric: Reliant

Water: Cable:

Propane:

Phone Company:

phone #:

(7) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer Da	te Signature of Buyer	Date
Printed Name:	Printed Name:	

Fax:

### Seller's Disclosure Explanations

#### Section 1

The dishwasher does not work.

The washing machine's water valves have corroded and need to be replaced.

#### Section 2

Crack in the living room sheetrock ceiling.

The main bedroom door hinge has broken out of the door frame.

The driveway has cracks.

Numerous holes in the sheetrock walls throughout the house.

A section of woodwork under the kitchen sink has been torn off.

First bedroom ceiling fan light chain won't pull.

The fireplace damper handle broke in the open position.

The kitchen window broke, and the storm window is still in place.

Utility room doors have holes.

#### Section 3

The contents of the toaster caught on fire, scorching the bottom of the kitchen cabinet.

The ballast in the kitchen light overheated, causing a small plastic fire to scorch a small section of the kitchen ceiling.

KJ VS