

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE PROPERTY AT	505 Pincrest St Avinger, Tx 75630
AS OF THE DATE SIGNED BY	OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR ISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER, AGENT.
Seller is is not occupying the Property? 9/1/2025 Property	e Property. If unoccupied (by Seller), how long since Seller has occupied (approximate date) or never occupied the
Section 1 The Property has the item	s marked below: (Mark Yes (Y), No (N), or Unknown (U),)

This notice does not establish the items to be conveyed. The contract will determine which items will & will not convey.

Item	Υ	N	U
Cable TV Wiring			×
Carbon Monoxide Det.		×	
Ceiling Fans	×		
Cooktop	×		
Dishwasher		×	
Disposal		×	
Emergency Escape Ladder(s)		×	
Exhaust Fans		×	
Fences	×		
Fire Detection Equip.	×		
French Drain		×	
Gas Fixtures	×		
Liquid Propane Gas:		×	
-LP Community (Captive)		×	
-LP on Property		×	

Item	Υ	N	U
Natural Gas Lines	×		
Fuel Gas Piping:		×	
-Black Iron Pipe		×	
-Copper		×	
-Corrugated Stainless Steel Tubing		×	
Hot Tub		×	
Intercom System		×	
Microwave	X		
Outdoor Grill		×	
Patio/Decking	×		
Plumbing System	×		
Pool		×	
Pool Equipment		×	×
Pool Maint. Accessories		×	
Pool Heater		×	

Item	Y	N	J
Pump: sump grinder		X	
Rain Gutters	×		
Range/Stove	×		
Roof/Attic Vents	×		
Sauna		×	
Smoke Detector			×
Smoke Detector - Hearing Impaired		×	
Spa		X	
Trash Compactor		×	
TV Antenna		×	
Washer/Dryer Hookup	×		
Window Screens	×		
Public Sewer System	×		

Item	Υ	N	U	Additional Information
Central A/C	×			electric gas number of units:
Evaporative Coolers	×			number of units:
Wall/Window AC Units		X		number of units:
Attic Fan(s)		X		if yes, describe:
Central Heat	×			electric 🔀 gas number of units: 1
Other Heat		X		if yes, describe:
Oven	×			number of ovens: electric _ gas _ other:
Fireplace & Chimney		X		wood gas logs mockother:
Carport	×			attached not attached
Garage		X		attached not attached
Garage Door Openers		X		number of units:number of remotes:
Satellite Dish & Controls		X		owned leased from:
Security System	·	X		owned leased from:

(TXR-1406) 07-10-23 Initialed by: Buyer:

Phone: (903)807-8801

Page 1 of 7

Fax:

505 Pincrest St

Concerning the Property at	Avinger, Tx 756

Solar Panels		X		owned leased from:
Water Heater	X			electric gas other: number of units:
Water Softener		×		owned leased from:
Other Leased Items(s)		×		if yes, describe:
Underground Lawn Sprinkler		×		automatic manual areas covered
Septic / On-Site Sewer Facility		×		if yes, attach Information About On-Site Sewer Facility (TXR-1407)
Roof Type: Metal	h T>	es (R-1	no 1906	JD co-op unknown other:
Are you (Seller) aware of any of	the			listed in this Section 1 that are not in working condition, that have
		no	ıı ye:	es, describe (attach additional sheets if necessary):

if you are aware and No (N) if you are not aware.)

Item	Υ	N
Basement		×
Ceilings		×
Doors		×
Driveways		×
Electrical Systems		×
Exterior Walls		×

Item	Υ	N
Floors		×
Foundation / Slab(s)		×
Interior Walls		×
Lighting Fixtures		×
Plumbing Systems		×
Roof		X

Item	Υ	N
Sidewalks		×
Walls / Fences		×
Windows		×
Other Structural Components		×

If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):

Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)

Condition	Υ	N
Aluminum Wiring		×
Asbestos Components		×
Diseased Trees: oak wilt		×
Endangered Species/Habitat on Property		×
Fault Lines		×
Hazardous or Toxic Waste		×
Improper Drainage		×
Intermittent or Weather Springs		×
Landfill		×
Lead-Based Paint or Lead-Based Pt. Hazards		×
Encroachments onto the Property		×
Improvements encroaching on others' property		×
		<u> </u>
Located in Historic District		×
Historic Property Designation		×
Previous Foundation Repairs		X

Condition	Υ	N
Radon Gas		×
Settling		×
Soil Movement		×
Subsurface Structure or Pits		×
Underground Storage Tanks		×
Unplatted Easements		×
Unrecorded Easements		×
Urea-formaldehyde Insulation		×
Water Damage Not Due to a Flood Event		×
Wetlands on Property		×
Wood Rot		×
Active infestation of termites or other wood		
destroying insects (WDI)		×
Previous treatment for termites or WDI		×
Previous termite or WDI damage repaired		×
Previous Fires		×

and Seller: (TXR-1406) 07-10-23 Initialed by: Buyer: _ UNITED COUNTRY H5 AUCTION AND, 401 MAGRILL ST. LONGVIEW TX 75601 Phone: (903)807-8801 Fax: Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com Joshua Rvan

505 Pincrest St

Concerning the Property at		Avinger, Tx 75630			
	Roof Repairs	×	Termite or WDI damage needing repair	>	
Previous	Other Structural Repairs	×	Single Blockable Main Drain in Pool/Hot		
			Tub/Spa*	>	
	Use of Premises for Manufacture	×			
oi ivietnar	nphetamine				
If the ans	wer to any of the items in Section 3 is y	/es, explain (a	attach additional sheets if necessary):		
*A sin	gle blockable main drain may cause a sucti	ion entrapment	hazard for an individual.		
Section 4	1 Δre you (Seller) aware of any i	tem equinm	ent, or system in or on the Property that	is in need	
of repair	r. which has not been previously	disclosed	in this notice?yes × no If yes, expl	ain (attacl	
additional	I sheets if necessary):	diodioodd i	youno in you, expin	am (attaol	
	· ,				
			ring conditions?* (Mark Yes (Y) if you are	aware and	
check wi	holly or partly as applicable. Mark No	ס (N) if you aı	re not aware.)		
Y N					
×	Present flood insurance coverage.				
×	Previous flooding due to a failure	e or breach	of a reservoir or a controlled or emergency	release o	
_ =	water from a reservoir.				
×	Previous flooding due to a natural flo	ood event.			
X	Previous water penetration into a str	ructure on the	Property due to a natural flood.		
×	Located wholly partly in a	100-year floo	odplain (Special Flood Hazard Area-Zone A, V	, A99, AE	
	AO, AH, VE, or AR).	•		,	
×	Located wholly partly in a 50)0-year floodp	olain (Moderate Flood Hazard Area-Zone X (shad	ed)).	
×	Located wholly partly in a flo	odway.			
_ × _ × _ ×	Located wholly partly in a flo	ood pool.			
×	Located wholly partly in a re	servoir.			
If the ans	wer to any of the above is yes, explain	(attach additi	onal sheets as necessary):		

*If Buyer is concerned about these matters, Buyer may consult Information About Flood Hazards (TXR 1414).

For purposes of this notice:

"100-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a special flood hazard area, which is designated as Zone A, V, A99, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding, which is considered to be a high risk of flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.

"500-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area, which is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding, which is considered to be a moderate risk of flooding.

"Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of Engineers.

(١X٢	₹-14	.06)	07-	10-23
---	-----	------	------	-----	-------

Initialed by: Buyer:

and Seller: DAY

Phone: (903)807-8801

Page 3 of 7

505 Pincrest St Avinger, Tx 75630

Concerning the Property at

"Flood insurance rate map" means the most recent flood hazard map published by the Federal Emergency Management Agency under the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seg.).

"Floodway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of a river or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as a 100-year flood, without cumulatively increasing the water surface elevation more than a designated height.

"Reservoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retain water or delay the runoff of water in a designated surface area of land.

Section 6. Have you (Seller) ever filed a claim for flood damage to the Property with any insurance provider, including the National Flood Insurance Program (NFIP)?* yes _x no If yes, explain (attach additional sheets as necessary):						
Even w	hen not required to the not required to the not risk flood	nd zones with mortgages fr I, the Federal Emergency zones to purchase flood	Management Agenc	y (FEMA) encoura	ages homeowners	in high risk, moderate
Administr	ation (SBA) f	(Seller) ever receiver flood damage to	the Property? _	_ yes 🔀 no		
	Are you (Se	eller) aware of any o	f the following?	(Mark Yes (Y) if you are av	ware. Mark No (N)
Y N		ons, structural modific unresolved permits, or n				
×		associations or mainter			complete the follo	owing:
	Name of a	association:			Phone:	
	Any unpa If the Pr	s name: ssessments are: \$ id fees or assessment for operty is in more than attach information to this	or the Property? n one association,	yes (\$) no	0
×	interest with o	area (facilities such a others. If yes, complete t nal user fees for commo	he following:	•	,	
×	Any notices use of the Pro	of violations of deed	restrictions or go	overnmental ord	dinances affectir	ng the condition or
<u>×</u>	•	or other legal proceed divorce, foreclosure, he		•	ting the Propert	y. (Includes, but is
	-	n the Property except ne condition of the Prope		caused by: n	atural causes, s	suicide, or accident
×	Any condition	on the Property which r	materially affects the	e health or safet	y of an individual	
×	environmenta If yes, atta	or treatments, other I hazards such as asbes ach any certificates or of on (for example, certifica	stos, radon, lead-ba ther documentation	sed paint, urea- identifying the e	formaldehyde, or extent of the	
×	-	r harvesting system lo		erty that is lar	ger than 500 ga	llons and that uses
(TXR-1406)	07-10-23	Initialed by: Buyer:	,8	and Seller: DAY	,	Page 4 of 7

UNITED COUNTRY H5 AUCTION AND, 401 MAGRILL ST. LONGVIEW TX 75601

Phone: (903)807-8801

Fax:

Page 4 of 7

Concerning the Property at			505 Pincrest St Avinger, Tx 75630			
	e Property is located ailer.	d in a propane gas syste	em service area owned by a propa	n service area owned by a propane distribution system		
If the answer to	any of the items in S	ection 8 is yes, explain (a	ttach additional sheets if necessary):			
persons who	regularly provide	inspections and wh	ler) received any written insp o are either licensed as insp If yes, attach copies and complete th	ectors or otherwise		
Inspection Date	Туре	Name of Inspecto	r	No. of Pages		
Section 10. Ch HomesteWildlife!	A buyer shoeck any tax exempto ead Management	ould obtain inspections fro ion(s) which you (Seller Senior Citizen	as a reflection of the current condition inspectors chosen by the buyer. currently claim for the Property:			
with any insura	ance provider? y	es 🔀 no	damage, other than flood dama			
example, an i	nsurance claim or		Is for a claim for damage to in a legal proceeding) and no including its proceeding.			
detector requi	irements of Chapte	er 766 of the Health a	detectors installed in accordant safety Code?* unknown	no yes. If no		
*Chanter	766 of the Health and S	afety Code requires one-fam	nily or two-family dwellings to have worki	na smoke detectors		

installed in accordance with the requirements of the building code in effect in the area in which the dwelling is located, including performance, location, and power source requirements. If you do not know the building code requirements in effect in your area, you may check unknown above or contact your local building official for more information.

A buyer may require a seller to install smoke detectors for the hearing impaired if: (1) the buyer or a member of the buyer's family who will reside in the dwelling is hearing-impaired; (2) the buyer gives the seller written evidence of the hearing impairment from a licensed physician; and (3) within 10 days after the effective date, the buyer makes a written request for the seller to install smoke detectors for the hearing-impaired and specifies the locations for installation. The parties may agree who will bear the cost of installing the smoke detectors and which brand of smoke detectors to install.

(TXR-1406) 07-10-23

Initialed by: Buyer:

and Seller: |/)//

Page 5 of 7

Fax:

505 Pin	cre	st St
Avinger.	Tx	75630

Concerning the Property at	Avinger, Tx 75630		
including the broker(s), has instructed or influenced material information.	are true to the best of Seller's belief and that no person, Seller to provide inaccurate information or to omit any		
Darrell Austin Youngblood 09/23/2025			
	Signature of Seller Date		
Printed Name:	Printed Name:		
ADDITIONAL NOTICES TO BUYER:			
determine if registered sex offenders are located	a database that the public may search, at no cost, to in certain zip code areas. To search the database, visit concerning past criminal activity in certain areas or		
feet of the mean high tide bordering the Gulf of M Act or the Dune Protection Act (Chapter 61 or 63 construction certificate or dune protection permit r	seaward of the Gulf Intracoastal Waterway or within 1,000 Mexico, the Property may be subject to the Open Beaches B, Natural Resources Code, respectively) and a beachfront may be required for repairs or improvements. Contact the er construction adjacent to public beaches for more		
Commissioner of the Texas Department of Ir requirements to obtain or continue windstorm a required for repairs or improvements to the Pr	of this state designated as a catastrophe area by the assurance, the Property may be subject to additional and hail insurance. A certificate of compliance may be operty. For more information, please review <i>Information Certain Properties</i> (TXR 2518) and contact the Texas rance Association.		
compatible use zones or other operations. Information available in the most recent Air Installation Compa	lation and may be affected by high noise or air installation ation relating to high noise and compatible use zones is atible Use Zone Study or Joint Land Use Study prepared the Internet website of the military installation and of the ation is located.		
(5) If you are basing your offers on square footage items independently measured to verify any reported in	e, measurements, or boundaries, you should have those formation.		
(6) The following providers currently provide service to the	Property:		
Electric: Upshur rural	phone #:		
Sewer: City	nhono #:		
Water: City	nhana #		
Cable:			
Trash:			
Natural Gas:	phone #:		
Phone Company: Kinetic			
Propane:	phone #:		
Internet: Kinetic phone #:			
	Authentision		

(TXR-1406) 07-10-23

Initialed by: Buyer:

and Seller:

Page 6 of 7

505 Pinecrest St.

Printed Name:

Concerning the Property at	505 Pincrest St Avinger, Tx 75630		
(7) This Seller's Disclosure Notice was completed by	y Seller as of the date signed. The brokers have relied reason to believe it to be false or inaccurate. YOU AIUR CHOICE INSPECT THE PROPERTY.		
The undersigned Buyer acknowledges receipt of the forego	ing notice.		
Signature of Buyer Date	Signature of Buyer Date		

Printed Name:

(TXR-1406) 07-10-23



Fax: