FORM NO. GWS-31 01/93	WELL CONSTRUCTION AND TEST REPORT STATE OF COLORADO, OFFICE OF THE STATE ENGINEER		For Office Use only MECENVED	
1. WELL PERMIT NUMBER _273814			MEA	28 A C M
Maili City,	WNER NAME(S) GEORGE LAVELLE failing Address PO BOX 130 city, St. Zip DIVIDE, CO 80814 hone (719) 687-3345		OCT 2 3 2007 WATER RESOURCES STATE ENGINEER GOLO.	
	LL LOCATION AS DRILLED: NW 1/4 SE 1/4, Sec. 15 Twp. 13 SOUTH , Range 70 WEST			
SUB		(east of	Sec. line. OR	_ FILING(UNIT)_5
1 1		LLING METHOD _		455 a
	DLOGIC LOG:	6. HOLE DIAM.	DEPTH COMPLE	τπ.
Depth 0-10 10-205	Description of Material (Type, Size, Color, Water Location) DECOMPOSED GRANITE GRANITE, BROWN & RED	8 5/8 6 1/8	(in.) From (ft) 0 40	To (ft) 40 700
205-340 340-480 480-500 500-700 REMARI MEASURI	GRANITE, BROWN & TAN GRANITE, GREY GRANITE, RED & TAN GRANITE, GREY KS: DEPTH, STATIC LEVEL AND PRODUCTION ED AFTER HYDROFRACTURE.	8. FILTER PACI Material N/A Size	Wall Size el	+1 40 10 375 395 415 435 455 375 395 415 435 415 435 ACKER PLACEMENT: e N/A th
DISINFECTION: Type Granular Chlorine Amt. Used 3 1/2 CUPS WELL TEST DATA: TESTING METHOD Air lift Static Level 78 ft. Date/Time measured 10/12/07 Pumping level 455 ft. Date/Time measured 10/12/07 Test length (hrs.) 2 Remarks				
3. I have read the statements made herein and know the contents thereof, and that they are true to my knowledge. [Pursuant to Section 24-4-104 (13)(a) CONTRACTOR Black Mountain Drilling, Inc. Phone (719) 687-5708 Lic. No. 1261				
	le (Please type or print) Wiley, Contractor Signature	aved W	ila	Date 10/15/07