

CALIBRATION CERTIFICATE

Table of Contents

1. Table of Contents	P	age 1
2. TRUCK - 22545 - Indicator	Р	age 2



CALIBRATION CERTIFICATE

LOCATION INFO		
Customer Name : BRIGGS ORCHARD	Customer Number: 24615	Case #: 13657
Location Address : 27197 S. BROOKERSON RD. WILLCOX AZ 85643 United States		Certificate #: 13657-7664
Location Contact : PM-Jason Carlton		Device License #:
Asset Name : TRUCK	Test Date: 07/31/2023	Next Due Date (ANNUAL): 07/31/2024

EQUIPMENT TESTED						
Device	Mfg	Make	Model	Serial Number	Capacity/Divisions/Units	SWS Equipment ID
Indicator		RICE LAKE	720i	1881800093	120000 / 20 / LB	22545
Component - Vehicle	Swsco	Sidewinder	7070 LPS	042153		26284

TESTING	RESULTS				
	INCR	DECR A	S FOU	ND	
	APPLIED	RESULT	ERROR	TOL	
Test 1	0	0	0	20	PASS
Test 2	5000	5000	0	20	PASS
Test 3	9000	9000	0	20	PASS
Test 4	13000	13000	0	40	PASS
Test 5	17000	17000	0	40	PASS
Test 6	13000	13000	0	40	PASS
Test 7	17000	17000	0	40	PASS
Test 8	21000	21000	0	60	PASS

	INCI	R/DECR	AS LEFT	Γ	
	APPLIED	RESULT	ERROR	TOL	
Test 1	0	0	0	0	PASS
Test 2	5000	5000	0	0	PASS
Test 3	9000	9000	0	0	PASS
Test 4	13000	13000	0	20	PASS
Test 5	17000	17000	0	20	PASS
Test 6	13000	13000	0	20	PASS
Test 7	17000	17000	0	20	PASS

CONDITIONS AFFECTING TEST RESULTS/COMMENTS

20 PASS

Test 8 21000 21000 0

Performed visual inspection on scale. Scale in very good working condition and well taken care of. Performed increase/decrease, section, and strain test on scale. Scale was on point with every test. Scale passed in accordance with handbook 44 standards at this time.

STANDARDS USED TRACEABLE TO NIST

PASS

Truck 43 1000lb weights and test cart.

SUMMARY

By signing below I am certifying this Calibration IS in compliance with the current edition of Handbook 44 tolerances

PASS

TEST METHOD USED

AS LEFT

IIIL

Handbook 44

Handbook 44

RSA#RSR#Seal#TechnicianCustomerAZ 149732525-UNKNOWN-Nicholas Mather