

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF WATER RESOURCES

Land-Based Systems Unit

William R. Snodgrass - Tennessee Tower

312 Rosa L. Parks Ave., 11th Floor Nashville, TN 37243-110

APPLICATION FOR WATER RESOURCES SERVICES APPLICANT COMPLETE QUESTIONS

1. Service Rec	quested (Check Service)		Fees Due			
X Septie	c System Construction Permit					
	Dwelling		\$ 400.00	PAID		
Commercial: gdp			\$			
_	System Modification		\$			
_	Repair		\$	_		
<u>X</u>		pection	\$ 100.00			
	ction Letter		\$	_		
	ficate of Verification		\$			
	r Sample					
_	Total Coliform		\$	_		
4.10	Fecal Coliform		s			
	native System Permit		\$			
	native Construction Inspection		\$			
	Conventional System Plan Revie	W	s			
	Alternative System Plan Review		S	_		
Experimental System Plan Review			S			
	ivision Evaluation: Lots:		S	-		
Pump	oing Contractor – Septage Applica	ion	\$			
2. LANDOWNER:		APPLICAN	T:	Site Add	iress:	
Names:	Ronnie Braden	Names:	Ronnie Braden	Adress:	7 Knobs Road	
Address:	7 Knobs Rd.	Address:	7 Knobs Rd.		Gainesboro, Tennes	see 38562
	gainesboro, Tennessee 3717	4	gainesboro, Tennessee 37174			
Day Phone:	6155094910	Day Phone:	6155094910			
Original Own	ner: Ronnie Braden	Email:	dale.braden@gmail.com			
b) In a subdi	vision? No	Give specific directions		uild site but soil	Land is currently being test has been marked	with ping
c) Tax Map	077		Parcel 031.01			
FOR SSDS 1 4. ONLY:	a) Size of lot <u>66.00</u>		of Bedrooms 3		Added	
c) How many		d) Excavated Basement	? Yes No _X	_		
		es No_X_				
	water used monthly (gallons)	10				
g) Water Sup						
h) Is the lot st		_ If not, date it will be		1 2021		
Is the hous)	If not, date	it will be staked: Jul 0	1, 2021		
i) Installer, if	CTION LETTER ONLY AND	CERTIFICATE OF VERH	FIGATION ONLY.			
a) Age of hou	wage system inspected	b) Is house vacant?	How long?			
d) Date of pre		Inc	pected			
	ter "backing up" into plumbing fix		Surfacing on the grour	nd9		
	ater including washing machines		Surfacing on the groun	IG.		
	R SAMPLE ONLYa) Source of		Well Otl	her		
	outside faucet?	c) Is the source chlorinated		iici		
	Is the casing 6" above the ground		Is a sanitary seal on the casing	?		
7. I certify that	the above information is true and or Environmental Services to the I	correct to the best of my kno	wledge; I have been authorize		name landowner to	submit this
DATE: May 1	1, 2021 SIGNATURE: R	onnie Dale Braden	AMOUNT PAID 500.00	RE	CEIPT NUMBER:_	3806675345

CN-0971 (Rev. 1-18) RDA's 2321 &2403