



This sketch represents a survey made on the ground. During the performance of this survey, persons working under my supervision observed conditions within and along the boundaries and to the best of my knowledge they are as shown. The location of visual structural improvements with respect to the boundary lines are as shown. This document is not valid for any purpose unless signed and sealed by a Registered Professional Land Surveyor.



ALL COUNTY SURVEYING, INC.
Tx. Firm No. 10023600
4330 South 5th Street
Temple, Texas 76502
254-778-2272, Killeen 254-634-4636
Fax 254-714-1608
www.allcountysurveying.com



Ray Michael Smith

Revised: 09-18-2019 to
revise slide building lines.

Survey
completed: 07-29-2019

Scale: 1" = 20'

Job No.: 190741

Dwg No.: 190741

Drawn by: SLW

Surveyor: RMS #6740

Plot Date: 09-18-2019

Plot Date: 09-18-2019