

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

**DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.****SECTION I - WATER SUPPLY**

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal ☐ Unknown  
☒ Drilled ☐ Dug ☐ Other \_\_\_\_\_

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the  
 (public/private/other) water system?

Pump (if any): ..... ☐ N/A ☐ Yes ☒ No ☐ Unknown  
 Quantity: ..... ☐ Yes ☒ No ☐ Unknown  
 Quality: ..... ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ..... ☐ Yes ☒ No  
 If Yes, Date of most recent test: \_\_\_\_\_ Are test results available? .. ☐ Yes ☒ No  
 To your knowledge, have any test results ever been reported as unsatisfactory  
 or satisfactory with notation? ..... ☐ Yes ☒ No  
 If Yes, are test results available? ..... ☐ Yes ☒ No  
 What steps were taken to remedy the problem? \_\_\_\_\_

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: just off right corner of front porch

Installed by: Jones of Ellsworth

Date of Installation: May 7, 2025

USE: Number of persons currently using system: 0

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: home has not been lived in for a few years

Source of Section I information: seller

Buyer Initials \_\_\_\_\_

Page 1 of 8

Seller Initials DEH/PSH

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655

## SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... ☐ Yes ☐ No

If Yes, what results: \_\_\_\_\_

Have you experienced any problems such as line or other malfunctions? ..... ☐ Yes ☐ No

What steps were taken to remedy the problem? \_\_\_\_\_

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: \_\_\_\_\_

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: \_\_\_\_\_

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: \_\_\_\_\_

Location: left of home OR ☐ Unknown

Date installed: unknown Date last pumped: unknown Name of pumping company: none

Have you experienced any malfunctions? ..... ☐ Yes ☒ No

If Yes, give the date and describe the problem: \_\_\_\_\_

Date of last servicing of tank: Unknown Name of company servicing tank: none

Leach Field: ..... ☒ Yes ☐ No ☐ Unknown

If Yes, Location: left of home

Date of installation of leach field: unknown Installed by: unknown

Date of last servicing of leach field: 05/07/2025 Company servicing leach field: none

Have you experienced any malfunctions? ..... ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy: \_\_\_\_\_

Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☒ No

If Yes, are they available? ..... ☐ Yes ☐ No

Is System located in a Shoreland Zone? ..... ☐ Yes ☒ No ☐ Unknown

Comments: \_\_\_\_\_

Source of Section II information: seller/prior disclosure

Buyer Initials \_\_\_\_\_

Page 2 of 8

Seller Initials LEHJHSC

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

| Heating System(s) or Source(s)                                                 | SYSTEM 1 | SYSTEM 2   | SYSTEM 3 | SYSTEM 4 |
|--------------------------------------------------------------------------------|----------|------------|----------|----------|
| TYPE(S) of System                                                              | HWBB     | wood stove |          |          |
| Age of system(s) or source(s)                                                  | unknown  | unknown    |          |          |
| TYPE(S) of Fuel                                                                | oil      | wood       |          |          |
| Annual consumption per system or source (i.e., gallons, kilowatt hours, cords) | unknown  | unknown    |          |          |
| Name of company that services system(s) or source(s)                           | unknown  | unknown    |          |          |
| Date of most recent service call                                               | unknown  | unknown    |          |          |
| Malfunctions per system(s) or source(s) within past 2 years                    | none     | none       |          |          |
| Other pertinent information                                                    |          |            |          |          |

Are there fuel supply lines? ..... ☒ Yes ☐ No ☐ Unknown

Are any buried? ..... ☐ Yes ☒ No ☐ Unknown

Are all sleeved? ..... ☐ Yes ☒ No ☐ Unknown

Chimney(s): ..... ☒ Yes ☐ No

If Yes, are they lined: ..... ☒ Yes ☐ No ☐ Unknown

Is more than one heat source vented through one flue? ..... ☒ Yes ☐ No ☐ Unknown

Had a chimney fire: ..... ☐ Yes ☐ No ☒ Unknown

Has chimney(s) been inspected? ..... ☐ Yes ☐ No ☒ Unknown

If Yes, date: \_\_\_\_\_

Date chimney(s) last cleaned: \_\_\_\_\_

Direct/Power Vent(s): ..... ☐ Yes ☐ No ☒ Unknown

Has vent(s) been inspected? ..... ☐ Yes ☐ No ☒ Unknown

If Yes, date: \_\_\_\_\_

Comments: \_\_\_\_\_

Source of Section III information: \_\_\_\_\_

**SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

**A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground storage tanks on the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, are tanks in current use? ..... ☐ Yes ☐ No ☐ Unknown

If no longer in use, how long have they been out of service? \_\_\_\_\_

If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ Unknown

Are tanks registered with DEP? ..... ☐ Yes ☐ No ☐ Unknown

Age of tank(s): \_\_\_\_\_ Size of tank(s): \_\_\_\_\_

Location: \_\_\_\_\_

Buyer Initials \_\_\_\_\_

Page 3 of 8

Seller Initials ECB/CHS \_\_\_\_\_

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655

What materials are, or were, stored in the tank(s)? \_\_\_\_\_

Have you experienced any problems such as leakage: ..... ☐ Yes ☐ No ☐ Unknown

Comments: \_\_\_\_\_

Source of information: seller**B. ASBESTOS** - Is there now or has there been asbestos:As insulation on the heating system pipes or duct work? ..... ☐ Yes ☒ No ☐ UnknownIn the ceilings? ..... ☐ Yes ☒ No ☐ UnknownIn the siding? ..... ☐ Yes ☒ No ☐ UnknownIn the roofing shingles? ..... ☐ Yes ☒ No ☐ UnknownIn flooring tiles? ..... ☐ Yes ☒ No ☐ UnknownOther: ..... ☐ Yes ☒ No ☐ Unknown

Comments: \_\_\_\_\_

Source of information: seller**C. RADON/AIR** - Current or previously existing:Has the property been tested? ..... ☐ Yes ☒ No ☐ Unknown

If Yes: Date: \_\_\_\_\_ By: \_\_\_\_\_

Results: \_\_\_\_\_

If applicable, what remedial steps were taken? \_\_\_\_\_

Has the property been tested since remedial steps? ..... ☐ Yes ☐ No ☐ UnknownAre test results available? ..... ☐ Yes ☐ No

Results/Comments: \_\_\_\_\_

Source of information: seller**D. RADON/WATER** - Current or previously existing:Has the property been tested? ..... ☐ Yes ☒ No ☐ Unknown

If Yes: Date: \_\_\_\_\_ By: \_\_\_\_\_

Results: \_\_\_\_\_

If applicable, what remedial steps were taken? \_\_\_\_\_

Has the property been tested since remedial steps? ..... ☐ Yes ☐ No ☐ UnknownAre test results available? ..... ☐ Yes ☐ No

Results/Comments: \_\_\_\_\_

Source of information: seller**E. METHAMPHETAMINE** - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

Comments: \_\_\_\_\_

Source of information: seller

Buyer Initials \_\_\_\_\_

Page 4 of 8

Seller Initials EEH/ESH

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655**F. LEAD-BASED PAINT/PAINT HAZARDS** - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? .....

..... Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: .....

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: .....

Are you aware of any cracking, peeling or flaking paint? ..... ☒ Yes ☐ No

Comments: .....

Source of information: trim needs repainting**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:TOXIC MATERIAL: ..... ☐ Yes ☒ No ☐ UnknownLAND FILL: ..... ☐ Yes ☒ No ☐ UnknownRADIOACTIVE MATERIAL: ..... ☐ Yes ☒ No ☐ Unknown

Other: .....

Source of information: seller**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.****SECTION V - ACCESS TO THE PROPERTY**Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☒ Yes ☐ No ☐ UnknownIf Yes, explain: Property has a ROW to a common area on the pondSource of information: deedIs access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☒ Yes ☐ No ☐ UnknownIf No, who is responsible for maintenance? subdivision ownersRoad Association Name (if known): Sandy Beach RetreatSource of information: deed

Buyer Initials \_\_\_\_\_

Page 5 of 8

Seller Initials <sup>EEHJZHSI</sup> \_\_\_\_\_

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: \_\_\_\_\_

Have any flood events affected a structure on the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: \_\_\_\_\_

Has any flood-related damage to a structure occurred on the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: \_\_\_\_\_

Has there been any flood insurance claims filed for a structure on the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: \_\_\_\_\_

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: \_\_\_\_\_

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ..... ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

**FIRMette**Relevant Panel Number: 23009C0475D Year: 2016 (Attach a copy)

Comments: \_\_\_\_\_

Source of Section VI information: seller/FIRMette

Buyer Initials \_\_\_\_\_

Page 6 of 8

Seller Initials EEH/JS

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655

## SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....  
☐ Yes ☒ No ☐ Unknown

If Yes, explain: \_\_\_\_\_

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☐ No ☐ Unknown

Are there any actual or alleged violations of a shoreland zoning ordinance including those that are imposed by the state or municipality? ..... ☐ Yes ☐ No ☐ Unknown

If Yes, explain: \_\_\_\_\_

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: \_\_\_\_\_

Year Principal Structure Built: 1993 What year did Seller acquire property? 2010

Roof: Year Shingles/Other Installed: 2004

Water, moisture or leakage: none

Comments: \_\_\_\_\_

Foundation/Basement:

Is there a Sump Pump? ..... ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ..... ☐ Yes ☒ No ☐ Unknown

Prior water, moisture or leakage? ..... ☐ Yes ☒ No ☐ Unknown

Comments: \_\_\_\_\_

Mold: Has the property ever been tested for mold? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? ..... ☐ Yes ☐ No

Comments: \_\_\_\_\_

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: \_\_\_\_\_ ☐ Unknown

Comments: \_\_\_\_\_

Has all or a portion of the property been surveyed? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ..... ☒ Yes ☐ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... ☐ Yes ☒ No ☐ Unknown

Modular ..... ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure ..... ☐ Yes ☒ No ☐ Unknown

Comments: \_\_\_\_\_

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: no real defects, but property is unfinished.

Comments: \_\_\_\_\_

Source of Section VII information: seller/visual

Buyer Initials \_\_\_\_\_ Page 7 of 8 Seller Initials EPH/MS

# National Flood Hazard Layer FIRMette



68°12'39"W 44°46'37"N



0 250 500 1,000 1,500 2,000 1:6,000 Feet

68°12'2"W 44°46'12"N

## Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

Without Base Flood Elevation (BFE)  
*Zone A, V, A99*

With BFE or Depth  
*Zone AE, AO, AH, VE, AR*

Regulatory Floodway

0.2% Annual Chance Flood Hazard, Area of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile  
*Zone Y*

Future Conditions 1% Annual Chance Flood Hazard  
*Zone X*

Area with Reduced Flood Risk due to Levee. See Notes.  
*Zone X*

Area with Flood Risk due to Levee  
*Zone D*

NO SCREEN

Area of Minimal Flood Hazard  
*Zone X*

Effective LOMRs

Area of Undetermined Flood Hazard  
*Zone X*

Channel, Culvert, or Storm Sewer

Levee, Dike, or Floodwall

Cross Sections with 1% Annual Chance Water Surface Elevation

Coastal Transect

Base Flood Elevation Line (BFE)  
*Zone X*

Limit of Study

Jurisdiction Boundary

Coastal Transect Baseline

Profile Baseline

Hydrographic Feature

Digital Data Available

No Digital Data Available

Unmapped

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards.

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on **4/18/2025 at 2:44 PM** and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

PROPERTY LOCATED AT: 116 Sandy Beach Lane, Otis, ME 04655**SECTION VIII - ADDITIONAL INFORMATION**Kitchen has a new range and cabinets, not put up. Most rooms are unfinished to some point.ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Earlin E. Hart Jr Earlin Hart Sr (Divisee)05/10/2025SELLER DATESELLER DATE**Earlin E. Hart Jr (Earlin Hard St divisee)**SELLER DATESELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATEBUYER DATEBUYER DATEBUYER DATEMaine Association of REALTORS®/Copyright © 2025.  
All Rights Reserved. Revised September 2024.

Page 8 of 8

